



## The Crystal Group, Distributions, LLC

**Main Office**  
3133 Monticello Place, Unit # 111, Orlando, FL 32835 Toll Free: (888) 553-3007 Fax: (413) 683-0361 Web site: www.kryton.com  
**Satellite Offices**  
New York, New Jersey, Florida, Georgia

### CHALLENGE

The Department of Environmental Protection (DEP), for New York City, Bureau of Waste Water Treatment, Jamaica Plant, had excessive ground water penetration within the stairwells of their building. Piping had been installed in the crack to direct penetrating water away from stairs area but it was insufficient to protect this passageway. A permanent solution to the leaking walls was required.



### PERFORMANCE

On July 1, 2001, The Crystal Group installed Kryton International's, "Krytol Specification No.1" crack repair system for repairing cracks, joints and holes in concrete. The system was installed to repair the Cold Joint area and included a coating of Kryton T1 and T2 Waterproofing on the surface. To Date the system is performing flawlessly.

#### OWNER

**NYC DEP Bureau of Waste Water Treatment**

#### LOCATION

**Jamaica, New York**

#### FOUNDATION CONTRACTOR

**The Crystal Group, LLC**

#### ARCHITECT

N/A

#### ENGINEER

N/A